

## **Hot Work Program**

## I. Purpose

The intent of the Hot Work Program is to define the rules for performing "hot work" as outlined in Occupational Safety & Health Administration (OSHA) 29 Code of Federal Regulations (CFR) 1910.252. These regulations will minimize the possibility of injury or property damage due to improper management of open flame/high temperature processes. See Appendix A for definitions.

## II. Hot Work Permit

- A. For any hot work that is performed in a location that is not designated as a hot work area, a hot work permit must be used. The Global Risk Consultants Permit, which is used on campus, is shown in Appendix B. The Fire Safety Supervisor (FSS), who is to be designated by the Physical Facilities Director, must be notified and is responsible for checking the area for fire-safe working conditions. See Appendix C for fire safety precautions. The FSS is also responsible for making sure that stand-by fire extinguishers are present, assigning a fire watch when necessary, and making certain that all personnel in the area are properly warned of the work to be done. The FSS will then issue a hot work permit.
- B. The fire safety supervisor will identify on the hot work permit:
  - a. The location and nature of the hot work
  - b. The name of the person (employee or contractor) doing the job
  - c. The expiration date and time
  - d. The emergency notification procedures
- C. The employee or contractor must submit the top copy of the permit to the FSS before work begins and hang the second page of the permit in a visible place in the work area; the permit is kept there until the job is completed, including the time allotted for the fire watch if one was needed. The first and second pages are the stapled together and filed in the maintenance shop.
- D. A fire extinguisher or, if suitable, a water hose must be kept in the immediate area of the work.



- E. The fire watcher observes the worker performing the hot work and keeps a constant vigil for stray sparks, ignition or other fire hazards. He/she must remain in the work area for at least a half hour after the work is done to check for smoldering fires.
- F. If the hot work will be done in a confined space, all confined space entry procedures must also be followed.
- G. The completed permit must be turned in at the end of the job to the FSS who files the records for the hot work program.

# III. Personal Protective Equipment

Protection of the eyes, face, neck, and hands is required during any type of hot work. A welding helmet and heavy insulated gloves provide some of this protection.

- A. Only natural fiber clothing should be worn on the upper body extremities. A leather apron or full body leathers is recommended.
- B. Respiratory protection is not required for most welding jobs if good ventilation is provided.
- C. Welding screens are required to protect adjacent workers from exposure to non-ionizing radiation. Adjacent workers are required to wear appropriate eye protection where screens are not feasible. Welder's assistants or anyone working in the screened area must wear appropriate eye protection.

## IV. Contractors

Contractors, their employees, agents and subcontractors must follow OSHA regulations that apply to their operation. If they do not have their own hot work program, the contractor must comply with the Montana Tech hot work program. In all cases, the Global Risk Consultants Hot Work Permit is used.

## V. Training

Required training will provided initially to new employees and whenever conditions or the program changes.

Reviewed: 2024



### **Appendix A: Definitions**

Hot work – any job activity that uses or produces flames, sparks, or heat that could act as an ignition source for any flammable liquid, gas or other combustible material in the area.

Fire watch – one or more people on the hot work job whose only purpose is to prevent a fire from starting from hot work performed in areas that are not designated as hot work areas or if any of the following conditions exist:

- Noticeable combustible materials, in building construction or contents, are closer than 35 feet to the point of operation or are easily ignited by sparks;
- Wall or floor openings within a 35-foot radius expose combustible material in nearby areas, including concealed spaced in walls or floors;
- Combustible materials are adjacent to the opposite side of metal partitions, walls, ceilings, or roofs and are likely to be ignited by conduction or radiation.

Fire watcher – person or persons who look for potential fires in all exposed areas during hot work and put out fires that are within the limits of the available fire extinguishers.



#### **Appendix B: Hot Work Permit**

Glob	al Risk Consultant	s® HOT WORK PERMIT
-		T WORK, ENSURE PRECAUTIONS ARE IN PLACE!
		JRE SPRINKLERS ARE IN SERVICE
		INGUISHERS ARE READILY AVAILABLE!
Hot Work Permit	is required for all operations	involving open flames or producing heat and/or sparks. This includes,
		ng, Soldering, Thawing Pipe, Torch-Applied Roofing, and Welding.
		There are no safer ways of effectively/efficiently doing this job.
Instructions		Required Precautions Checklist
The second s		Available sprinklers, hose streams, and extinguishers are in service/ operable
The Permit-Authorizing Individual must:		
<ul> <li>a) Verify precautions listed at right (or do not proceed with the work)</li> </ul>		Hot Work equipment in good repair
b) Complete and retain this page		Requirements within a 35 foot "sphere" of work:
<li>c) Give the second page to the person doing the work.</li>		<ul> <li>Combustible dust or lint-producing equipment, fans, and conveyors isolated or shut down</li> </ul>
Who, When, and Where?		Combustible/llammable materials removed, including: dust, lint, oil deposits (from all surfaces), packaging or stored materials, and flammable/combustible liquids.
Hot Work Being Done By		Floor swept clean
Contractor		Combustible floor wet down, covered with damp sand or fire-resistant
Date	Job Number	sheets     Remove other combustibles where possible. Otherwise protect with
		fire-resistant tarpaulins or metal shields
Location/Building and	1 Floor	All wall and floor openings covered
		Fire-resistant tarpaulins suspended beneath work
Nature of Job/Object		Potentially hazardous atmosphere(s) eliminated?
Name of Person Doing Hot Work		Work on walls/ceilings or enclosed equipment:
		Construction is noncombustible. No combustible covering or
		insulation  Combustibles on other side of walls moved away
I verify the above location has been examined, the		Enclosed equipment cleaned of all combustibles
precautions checked on the Required Precautions Checklist have been taken to prevent fire, and		Containers purged of flammable liquids/vapors
permission is authorized for work.		Fire watch/hot work area monitoring requirements:
Signature of Permit-Authorizing Individual		Fire Watch will be provided during and for minutes after work, in-
		cluding all coffee or lunch breaks
		Fire Watch is supplied with suitable extinguishers, charged small hose
Permit Expiration		Fire Watch is trained in the use of this equipment and in sounding alarm
Expiration Date	Expiration Time AM	Include additional watch for adjoining areas, above, or below
20	CI PM	Monitor hot work area periodically for hours after job is completed
		Atmospheric Monitoring
		Periodic atmospheric monitoring required?
THIS PERMIT IS GOOD FOR		Frequency:Min.
		Lower Explosive Limit less than% LEL
ONE	DAY ONLY!	Other precautions taken:
Rev. 5/2013		Confined Space or Lockout/Tagout permit completed if needed
		Area smoke or heat detection had been disabled if present
		Other



### **Appendix C: Fire Safety Precautions for Hot Work**

- Establish whether or not it is practical to move the work to a safer location.
- Clear the area surrounding the work of hazards up to a 35-ft radius.
- Sweep floors clean. Clean and remove grease and oils.
- Where practical, stop other operations and processes involving flammable or combustible material.
- Where practical, remove all flammable or combustible material from the work area; do not just seal the containers.
- Cover combustible and flammable materials that cannot be removed with fire resistant material, and isolate the area with welding curtains, if practical.
- Close all manhole covers or other openings in vessels that contain flammable liquids in the area.
- Remove or protect all cylinders containing compressed gases in the area.
- Close all doors and fire doors to prevent sparks from escaping.
- Make sure automatic sprinkler protection is in service and fully operational, if available.
- Keep hot work equipment in good repair. Check all hoses and their attachments for cracks and leaks.
- When performing hot work on walls and ceilings, move combustibles away from the opposite side.
- Evaluate all sewers within 50 ft. of the work area for the possibility of flammable vapors.
- Isolate the hot work or ignition source work site from other hazardous areas. Close doors, seal cracks in walls, floors, and doors, and seal trenches.
- Prohibit chlorinated solvents from use in or adjacent to all welding operations. Decomposition products such as phosgene can be formed as a result of the reaction of these solvent vapors with the radiation energy produced during welding operations.

Other alternatives to hot work should be considered if:

- Processes involving flammable liquids, gases and dusts cannot be shut down and made safe.
- Partitions, walls, ceilings or roofs have combustible coverings; for example, expanded plastic insulation.
- Partitions are made of combustible sandwich-type construction.
- Pipe or other metals can conduct enough heat to ignite nearby combustibles.
- Large amount of combustible materials is difficult to move or cover such as roll paper, cotton or jute storage.