

Channel Dynamics for the Madison River Downstream from Earthquake Lake, Montana

In cooperation with the Madison River Fisheries Technical Advisory Committee

Katherine J. Chase Peter McCarthy

U.S. Department of the Interior U.S. Geological Survey




Location





To West Yellowstone




Hebgen Lake Earthquake

- August 17, 1959
 7.3 Magnitude
- Hebgen Lake tipped - 15-20 foot waves and one shore now higher than other
- Other phenomena





≥USGS








Madison Slide and Earthquake Lake







Madison River Below Quake Lake



 Erosion and property damage 1970, 1971, 1986

 1972 USACE study recommended Hebgen Lake managed for 3,500 cfs flow threshold _____



<image>

Question: Can 3,500 cfs threshold be increased?

- Difficult to maintain 3,500 cfs threshold because of 2 large tributaries
- Higher Flows could benefit blue ribbon trout fishery downstream










Miles

 Determine amount of lateral and vertical channel movement since 1972
 Provide hydraulic analyses so that FWP can determine if 3,500 cfs threshold can be increased



1. HISTORICAL CHANNEL MOVEMENT



Aerial Photography: Upper Study Reach

2006







Photo comparisons: Section 1100





Madison River Approximate Thalweg Profiles






Why is thalweg approximate?












Aerial Photography: Lower Study Reach

2006












Peak flows



≥USGS

Peak flows and channel movement


HYDRAULIC ANALYSIS



Little River Research and Design (LRRD), Missouri Department of Conservation, The US Environmental Protection Agency Region VII, Missouri Department of Natural Resources.

HYDRAULIC ANALYSIS


Distribution of streambed-material particle size for Madison River below Quake Lake



◆ Top of reach near spillw ay betw een XS 1 & 2




Channel Materials




Flow Forces

Shear Stress = f(channel geometry, flow velocity)


han and the state





Boundary shear stresses (3,500 ft³/s) **≊USGS** and critical shear stresses

Average boundary shear stress and critical shear stresses along the channel




≥USGS

Additional factor: steep channel side slopes









Preliminary Conclusions

- FROM CHANNEL SURVEY
 - Channel degraded up to 10 feet since 1972
- FROM AERIAL PHOTOGRAPHY
 - Channel increased sinuosity (and decreased slope) since 1972
 - Magnitude of channel movement decreased from 1986-2006
 - Channel moved as recently as 2005



Preliminary Conclusions (cont.)

FROM HYDRAULIC ANALYSES

Shear stresses generated by the 3,500 ft³/sec threshold flow fall within ranges of critical shears stresses necessary to move D50 and larger material



Preliminary Conclusions (cont.)

LIMITATIONS

- Could not sample channel material through middle of channel; larger materials probably are present
- Calculated critical shear stresses from general relationships, not site-specific to shape and size distribution of the Madison channel materials

≈USGS

Madison Slide Info – USGS Photographic Library http://libraryphoto.cr.usgs.gov/index.html





USGS Home Contact USGS Search USGS

U.S. Geological Survey Photographic Library

Home | About the USGS Photo Library | Resolutions and Downloading | Contact Us |

Select a Welcome to the U.S. Geological tips Search Survey Photographic Library Method: Key Word Search This site is designed to provide free viewing and downloading of Earthquakes the entire USGS photographic collection. Mines, Mills, "Select a Search Method" menu accesses the photographs. Ouarries The "Key Word Search" feature allows the user the freedom to search for any desired subject. Choosing from the list of Mount St. subjects on this menu allows searching within specific Helens categories. National Parks Images are available to view and download at no charge. Terms of Use, Copyright, and Publishing Information. Photographers Digital resolution options of each image include: Pioneer Photographers 100 dots per inch (dpi) thumbnail-resolution GIF file Portrait 700 dpi medium-resolution JPG file Collection 1400 dpi high-resolution JPG file 1600+ dpi full-resolution JPG file For more information, visit Resolutions and Downloading at the top of this page.



Mount Rainier National Park, Washington. The Nisqually valley below Nisqually Glacier, as seen from station 3. Aggradation on the flood plain, caused by the outburst flood of October 25, 1955, is evidenced by altered topography and dead trees. A new bridge was constructed high above the floodaffected channels. August 31, 1965. Figure 38, U.S. Geological Survey <u>Professional Paper 631</u>.

Second Second Second

100%

Madison Slide Info

The Hebgen Lake, Montana Earthquake of August 17, 1959

GEOLOGICAL SURVEY PROFESSIONAL PAPER 435

Cooperating Agencies:

Geological Survey, U.S. Department of the Interior National Park Service, U.S. Department of the Interior Coast and Geodetic Survey, U.S. Department of Commerce Forest Service, U.S. Department of Agriculture







